Exception Sheet – Pre Departure

Model and Hull Number

To be completed by Captain before departure Scan copy to be sent to UK office

Date	Description	Referenc e No.	Repaired by
12/1/20	NO OUTBOARD MOTOR OR OUTBOARD FUEL TANK		
12/1/20	CHIP ON WOOD NEAR COMPASS		
12/1/20	Clear Vinyl on Dodger heavily scratched		
12/1/20	Glue or Epoxy on forward hatch		
12/1/20	Ice Box / Fridge not cooling well - left on overnight and did no remain cold		
12/1/20	Perkins Fuel Filter rusted / corroded in spares box		
12/120	Stitching in Mainsail near clew unraveling		

Notes

Captain

Justin Hoys-House Signature

Date <u>12/02/2020</u>

Justin Hoye-House

Name