

## PROCES VERBAL DE LIVRAISON DELIVERY CERTIFICATE

### DISTRIBUTEUR / DEALER

Nom	Catamaran Sales Inc.
Adresse	4005 N Federal Highway, Suite 200 Fort Lauderdale, FL 33308




### PROPRIETAIRE / OWNER

Nom	Dragonfly Investments Inc
Adresse	Trident Chambers, PO Box 146 Road Town, Tortola, BVI
Email	<a href="mailto:jmcoody4444@gmail.com">jmcoody4444@gmail.com</a>

### BATEAU / BOAT

Type	Lagoon 620
n° de Coque HIN / HIN Hull number:	IRIZK115L617

DATE :

DISTRIBUTEUR / DEALER	PROPRIETAIRE / OWNER
 THE CATAMARAN COMPANY	<p>MARU WORTHINGTON - CAPTAIN ON BEHALF OF JEFF MOODY - OWNER</p>
Catco Rep: 	Signature: 



# 2017 MODEL LAGOON 620

Exhibit A

## PROVISIONAL PRICING

BASE	A2016	OWNER (4 cabins, 4 heads), Central Galley, 2 x 110HP Volvo Penta D3-110	<input type="checkbox"/>
		OWNER (4 cabins, 4 heads), Lateral Galley, 2 x 110HP Volvo Penta D3-110	<input type="checkbox"/>
		OWNER (5 cabins, 5 heads), Central Galley, 2 x 110HP Volvo Penta D3-110	<input checked="" type="checkbox"/>
		OWNER "ESSENCE" (4 cabins, 4 heads), Central Galley, 2 x 110HP Volvo Penta D3-110	<input type="checkbox"/>
		OWNER "ESSENCE" (4 cabins, 4 heads), Lateral Galley, 2 x 110HP Volvo Penta D3-110	<input type="checkbox"/>
		OWNER "ESSENCE" (5 cabins, 5 heads), Central Galley, 2 x 110HP Volvo Penta D3-110	<input type="checkbox"/>
		CHARTER (5 cabins, 5 heads), Lateral Galley, 2 x 110HP Volvo Penta D3-110	<input type="checkbox"/>
		CHARTER (6 cabins, 6 heads), Central Galley, 2 x 110HP Volvo Penta D3-110	<input type="checkbox"/>
		CHARTER "ESSENCE" (5 cabins, 5 heads), Lateral Galley, 2 x 110HP Volvo Penta D3-110	<input type="checkbox"/>
CHARTER "ESSENCE" (6 cabins, 6 heads), Central Galley, 2 x 110HP Volvo Penta D3-110	<input type="checkbox"/>		
INTERIOR WOOD		INTERIOR WOOD IN GLOSSY ALPI TEAK with OAK FLOOR	<input type="checkbox"/>
		INTERIOR WOOD IN MAT ALPI TEAK with OAK FLOOR	<input type="checkbox"/>
AMBIANCE		AMBIANCE by NAUTA DESIGN	<input type="checkbox"/>
		HULL COLORED GELCOAT - LIGHT GREY HULL STICKER	<input checked="" type="checkbox"/>
UPHOLSTERY/CURTAINS		CARPET IN THE SALON	<input type="checkbox"/>
		CURTAINS ON SALON DOOR & AFT WINDOW	<input type="checkbox"/>
		ELECTRICAL PLEATED BLINDS IN SALON	<input type="checkbox"/>
		FITTED CARPET IN THE CABINS	<input type="checkbox"/>
		PLEATED BLINDS FOR AFT COMPANIONWAYS	<input checked="" type="checkbox"/>
		PLEATED BLINDS IN CABINS	<input checked="" type="checkbox"/>
		PLEATED BLINDS IN SALON	<input checked="" type="checkbox"/>
SPECIAL UPHOLSTERY: LEATHER IN SALON & SETTEES	<input type="checkbox"/>		
RIGGING & SAILS		ASYMETRIC SPINNAKER GEAR (not with Code 0)	<input type="checkbox"/>
		ASYMETRIC SPINNAKER 3,229 sq ft with SOCK	<input type="checkbox"/>
		BLACK PAINTED ALUMINUM MAST + BLACK CARBON CANOE BOOM with LIGHTS	<input type="checkbox"/>
		BLACK PAINTED ALUMINUM MAST + BOOM	<input type="checkbox"/>
		CARBON MAST & CARBON CANOE BOOM	<input type="checkbox"/>
		WHITE PAINTED ALUMINUM CANOE BOOM & COVER	<input checked="" type="checkbox"/>
		CARBON CANOE BOOM & COVER	<input type="checkbox"/>
		CODE 0 in BLACK MYLAR 2002 sq.ft.	<input type="checkbox"/>
		CODE 0 in D4 BLACK with KING ROPE	<input type="checkbox"/>
		CODE 0 RIG & POLE	<input checked="" type="checkbox"/>
		DACRON STAYSAIL & RUNNING RIGGING & HALYARD with ELECTRIC FURLER	<input checked="" type="checkbox"/>
HYDRANET SQUARETOP MAINSAIL & GENOA in lieu of Standard	<input checked="" type="checkbox"/>		
HYDRANET STAYSAIL + RUNNING RIGGING & HALYARD + ELECTRIC FURLER	<input checked="" type="checkbox"/>		
LAZY BAG WITH COVER BLUE, FACTORY INSTALLED	<input type="checkbox"/>		
DOYLE LAZY BAG STACK PAK	<input type="checkbox"/>		
2 STAND UP BLOCKS ON BOWS	<input checked="" type="checkbox"/>		
EXTERIOR UPHOLSTERY		2 SUNLOUNGER PADS FOR FOREDECK	<input type="checkbox"/>
		FOREDECK CUSHIONS	<input type="checkbox"/>
		AFT COCKPIT & AFT BEAM CUSHIONS	<input checked="" type="checkbox"/>
		SUNLOUNGER PADS FOR FLYBRIDGE	<input checked="" type="checkbox"/>
		FLYBRIDGE CUSHIONS	<input checked="" type="checkbox"/>

SBU

llw





CONTRÔLE TECHNIQUE  
TECHNICAL CHECK-LIST

N° de Coque HIN / HIN Hull number: IRZK1151.617

Opérations de mise en service / Commissioning operations		0 / X /	COMMENTAIRES / REMARKS
		ELECTRICITE /	ELECTRICITY
1	Coupe batterie / Batteries		
2	Tableau électrique	0	
3	Eclairage Intérieur	0	
4	Feux de nav. / mouillage / port	0	
5	Circuit 24V	0	
6	Circuit 220V	0	
7	Electronique de navigation	0	
		PLUMBERIE /	PLUMBING
8	Vanues et passe coques	0	
9	Pompe circuit eau douce	0	
10	Jauges réservoirs d'eau	0	
11	Pompes électriques d'assèchement	0	
12	Pompes manuelles d'assèchement	0	
13	Fonctionnement des WC	0	
14	Vanues évacuation Holding tank	0	
15	Circuit gaz / bouteille	0	
16	Chaufe eau	0	
		AMENAGEMENT, EQUIPEMENT /	LAYOUT EQUIPMENT
17	Portes, Equipets, Tireins, serrures	X	
18	Matelas, Salière, Capotonnage	0	SEE RESERVE LIST FOR OUTSTANDING ITEMS
19	Glaçiers, Frigo etc.	0	
20	Appareil de cuisson, four	0	
		PROPULSION, APPAREIL A GOUVERNER /	ENGINE, STEERING SYSTEM
21	Circuit combustible	0	
22	Niveau d'huile moteur	0	
23	Niveau d'huile inverseur	0	
24	Niveau liquide de refroidissement	0	
25	Tension des courroies	0	
26	Ouverture des prises d'eau	0	
27	Jauge carburant	0	
28	Ventilateur de cale	0	
29	Moteur et instrumentation moteur	0	
30	Commande accélérateur - inverseur	0	
31	Echappement	0	
32	Hélice, anodes	0	
33	Appareil à gouverner	0	
34	Nbre d'heures moteur bord	0	
35	Nbre d'heures moteur tribord	3	
		ACCOSTILLAGE COQUE et PONT /	GEAR DECK, DECK & HULL
37	Mât greement dormant, réglage	0	
38	Gondoles, ridoirs, serrage manilles	X	STAYSON FLUTEA HOUSING DAMAGED SEE RESERVE
39	Balçou, Fibres, Chandelliers	0	SEE RESERVE - TRANSON LIFE LINES MISTAKE X 2
40	Pouillage, accostillage de pont, vitrages	0	

N° de Coque HIN / HIN Hull number: IRZK1151.617

5810

MMDD

41	Gleement courant	Running rigging			
42	Entrouleur voiles	Furlet, seals in place		0	
43	Fermeaux de pont, hublots aération	Hatches, portholes, ventilation		0	
44	Sellerie extérieur	Cockpit cushions		0	
45	Grindeau, mouillage	Winches, anchoring		0	
46	Amarrures (x4) et pare bagages	Dock line (x4) and fenders		0	
<b>COSMETIQUE Intérieur-Extérieur / COSMETIC Inside-Outside</b>					
51	RAYURES bois Cab av	Wood scratch Forward cab	PT or STB	0	
52	RAYURES bois Cab Ar	Wood scratch Aft cab	PT or STB	0	
53	RAYURES bois Cab milieu	Wood scratch middle cab	PT or STB	0	
54	RAYURES bois carré	Wood scratch Saloon		0	
55	RAYURES bois Cuisine	Wood scratch Galley		0	
56	RAYURES bois Cockpit	Wood scratch cockpit		0	
57	DEFAULTS Gelcoat POINT-COQUE	Gelcoat Default DECK - HULL		0	
58	DEFAULTS Gelcoat COCKPIT	Gelcoat Default COCKPIT		0	
59	DEFAULTS Gelcoat FLY	Gelcoat Default FLY		0	
60	DIVERS remarques	Others		0	
<b>OPTION SPECIFIQUE / SPECIFIC OPTION</b>					
47	Voir l'inventaire du bateau	To be checked with boat's inventory		X	SEE INVENTORY LIST - CAN WEINER GALLEY & CUNNINGHAM CABIN. MISSING FLY BRIDGE FURNITURE
<b>DOCUMENTS</b>					
48	Rentree de l'inventaire	Inventory		0	
49	Rentree du Manuel CE	EC Manual		0	
50	Doc. techniques du bord	Technical documentations		0	
51	Doc garantie moteur / Raymarine	Warranty doc Engine and Raymarine		0	

Les Rubriques concernant ces opérations seront portées par l'apposition des mentions suivantes / The headings concerning each operations should be marked as follows

X Si le montage et/ou le fonctionnement de l'appareil ou de l'équipement est défectueux. A préciser en « Remarques/Observations » dans la colonne concernée.  
If the installations and / or functioning of the object is defective. To be noted in the appropriate "Observation" column.

0 Si le montage et/ou le fonctionnement de l'appareil ou de l'équipement est bon.  
If the installations and / or functioning of the object is good.

N Si le bateau et ses équipements ne sont pas concernée par la rubrique.  
Does not apply

BORDEAUX le: *Dec 21, 2016*  
CATCO REP -

*Scott Lancaster*


OWNER: *D. C. W. J.*  
*Dec 21st, 2016*

*SEE ATTACHED RESERVE*  
*(SBU)*

## L620 #115 RESERVE LIST

1. Gaz ram fly bridge counter to be installed.
2. 620 Decal #6 to be supplied and installed.
3. Swim ladder (2) receivers to be installed.
4. Extra camping gaz bottle.
5. Spare mainsail fuse.
6. Transom (2) lower lifelines to be supplied and installed.
7. Fly bridge chairs (2) and coffee table to be supplied.
8. Salon window scratch polishing.
9. Caulk line salon galley aft.
10. Excess caulk removal owner's cabin ceiling.
11. Owner head locker to be adjusted fit.
12. Owner under bunk drawer needs new soft catch.
13. Port forward companionway locker needs new soft catch.
14. Staysail furler cover to be repaired or replaced.
15. Watermaker to be proven good water.
16. Post initial navigation caulking as needed.
17. Outside cushion fit and count to be verified.

  
\_\_\_\_\_  
Scott Vanerstrom

  
\_\_\_\_\_  
Mark Worthington

DEC 21, 2016  
Date

DEC 21, 2016.  
Date